

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good** (0-3), **Fair** (4-6), **Poor** (7-9), and **Incomplete** (*). NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
156	Andrews Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
157	Andrews Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
321	Andrews Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall Only	Masonry	Fair	Yes	4	Inlet - Minor sediment and debris blocking. Outlet - Minor erosion.
322	Andrews Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
323	Andrews Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
324	Andrews Rd	Round- open 18in	Plastic	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	None		Good	No	0	
325	Andrews Rd	Round- open 12in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
3	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Wingwalls Only	Masonry	Good	No	0	
4	Archertown Rd	NS	Plastic	Poor	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Poor	Yes	Headwall w/ Wingwalls	Masonry	Poor	Yes	9	Inlet - Vegetation and debris blocking inlet. Pipe - Unable to see pipe and assess buried on outlet side. Outlet - Fallen in blocking pipe.
6	Archertown Rd	Round- open 15in	Metal	Fair	No	0-2'	Catch Basin	Precast Concrete	Good	No	Headwall w/ Wingwalls	Masonry	Fair	No	2	
7	Archertown Rd	Round- open 24in	Metal	Poor	Yes	5-10'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	5	Inlet - Wingwall erosion from road. Pipe - Corroded through bottom.
8	Archertown Rd	Round- open 15in	Metal	Fair	No	0-2'	None	N/A	Good	No	None		Good	No	1	
9	Archertown Rd	Round- open 12in	Metal	Fair	Yes	2-5'	None	N/A	Good	No	Headwall Only	Masonry	Good	No	2	Pipe - Half clogged throughout.
10	Archertown Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
11	Archertown Rd	Round- open 18in	Plastic	Poor	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall Only	Masonry	Fair	Yes	5	Pipe - Blocked and clogged and deformed outlet side. Outlet - Pipe causing collapse.
12	Archertown Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	2	Pipe - Half clogged on outlet side.
13	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
14	Archertown Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Poor	Yes	5	Inlet - Wingwall fallen in. Outlet - Scour undermining.
15	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
17	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	0	
19	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
21	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Fair	Yes	2	Outlet - one wingwall fallen in minor erosion.
22	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
23	Archertown Rd	Round- open 14in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	2	Pipe - A little clogged; some rust.
25	Archertown Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	2	Pipe - 1/3 clogged with sediment and debris.
26	Archertown Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	0	Inlet - driveway culvert erosion.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
27	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
29	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
30	Archertown Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall Only	Other	Fair	Yes	2	Outlet - Partially clogged and vegetation.
31	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	No	None		Good	No	1	
32	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
33	Archertown Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
34	Archertown Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	Yes	2	Outlet - Partially fallen in erosion.
35	Archertown Rd	Round- open 18in	Metal	Poor	Yes	2-5'	None	N/A	Fair	Yes	Headwall w/ Wingwalls	Other	Good	No	5	Inlet - Fallen in. Pipe - Rusted through.
36	Archertown Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	Yes	2	Outlet - Headwall fallen in.
37	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Poor	Yes	Headwall w/ Wingwalls	Other	Good	No	3	Inlet - Displaced obstructing culvert.
38	Archertown Rd	Round- open 18in	Plastic	Good	No	2-5'	None	N/A	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
39	Archertown Rd	Round- open 18in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Fair	No	2	Pipe - Starting to rust. Outlet - Perched.
40	Archertown Rd	Round- open 18in	Plastic	Poor	Yes	0-2'	None	N/A	Good	No	Headwall w/ Wingwalls	Other	Fair	Yes	5	Pipe - Collapse mid pipe blocking flow. Outlet - Some rock displacement.
41	Archertown Rd	Round- open 18in	Plastic	Good	No	0-2'	Wingwalls Only	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
43	Archertown Rd	Round- open 16in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
292	Archertown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Fair	No	1	
295	Archertown Rd	Round- open 24in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	1	Pipe - Inlet of pipe eroded outlet looks rehabilitated.
297	Archertown Rd	Round- open 15in	Plastic	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	2	Pipe - Clogging throughout almost fully blocked on inlet side.
193	Baker Rd	Round- open 24in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall Only	Other	Good	No	4	Inlet - Minor erosion. Pipe - Clogged open height 16 inches.
195	Baker Rd	Round- open 24in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Fair	No	1	
196	Baker Rd	Round- open 18in	Plastic	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Good	Yes	Headwall w/ Wingwalls	Other	Poor	Yes	6	Inlet - Vegetation impacting flow. Pipe - Caving in the middle road damage in photos. Outlet - Erosion.
197	Baker Rd	Round- open 18in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	None		Poor	Yes	6	Inlet - Minor erosion. Outlet - Erosion.
198	Baker Rd	Round- open 18in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Fair	No	None		Good	No	2	
199	Baker Rd	Round- open 12in	Metal	Fair	Yes	0-2'	Headwall Only	Other	Fair	Yes	Headwall Only	Other	Poor	Yes	7	Inlet - Erosion. Pipe - Pipe inlet deformed. Outlet - Headwall fallen in.
200	Baker Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Good	No	0	
202	Baker Rd	Round- open 15in	Metal	Poor	Yes	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	No	4	Pipe - Bottom corroded out.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
338	Baker Rd	Round- open 18in	Plastic	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Fair	No	1	
339	Baker Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	None		Good	No	2	Inlet - Head wall in danger of falling in.
349	Baker Rd	Round- open 24in	Metal	Poor	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Wingwalls Only	Other	Fair	No	6	Inlet - Minor erosion. Pipe - Pipe corroded.
281	Bean Brook Rd	Round- open 15in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall Only	Masonry	Fair	Yes	4	Pipe - Clogged 3/4. Outlet - Falling in.
282	Bean Brook Rd	NS		Poor	Yes	0-2'	None	N/A	Poor	Yes	None		Poor	Yes	9	Inlet - Buried. Pipe - Clogged on both ends cannot see pipe. Outlet - Blocked.
283	Bean Brook Rd	Round- open 12in	Plastic	Good	No	0-2'	Headwall Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
284	Bean Brook Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
285	Bean Brook Rd	Round- open 12in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
286	Bean Brook Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Wingwalls Only	Masonry	Good	No	0	
53	Blackberry Hill Rd	Round- open 24in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Good	No	0	
54	Blackberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	0	
55	Blackberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	0	
56	Blackberry Hill Rd	Round- open 12in	Metal	Poor	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	No	Headwall w/ Wingwalls	Other	Poor	Yes	7	Pipe - Bottom eroded. Outlet - Fallen in and blocking outlet of pipe.
57	Blackberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
58	Blackberry Hill Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
59	Blackberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
60	Blackberry Hill Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Minor Erosion.
61	Blackberry Hill Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
296	Blackberry Hill Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall Only	Other	Good	No	Headwall Only	Other	Good	No	0	
49	Brook Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Concrete	Good	No	Headwall w/ Wingwalls	Concrete	Poor	Yes	3	Outlet - Breaking apart large cracks risk of falling.
312	Brook Rd	NS	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	5	Inlet - Sediment and rocks obstructing inlet. Pipe - Pipe is completely clogged with rock and sediment.
301	Creamery Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
48	Dublin Rd	Round- open 15in	Metal	Fair	Yes	0-2'	None	N/A	Good	No	None		Good	No	2	Pipe - Sediment throughout ha,f clogged at outlet.
265	Dublin Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Erosion risk of collapse.
266	Dublin Rd	Round- open 15in	Metal	Good	No	5-10'	Headwall w/ Wingwalls	Masonry	Poor	Yes	None		Fair	Yes	5	Inlet - Fallen in blocking inlet. Outlet - Erosion all around culvert eating back toward road.
268	Dublin Rd	Round- open 15in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Outlet - Erosion.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
298	Dublin Rd Ext	NS		Poor	Yes		NS		Poor	Yes	Headwall Only	Masonry	Good	No	6	Inlet - Buried and vegetation. Pipe - Fully clogged cannot find.
203	East Cemetery Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
204	East Cemetery Rd	NS	Metal	Poor	Yes	0-2'	None	N/A	Fair	Yes	None		Fair	Yes	7	Inlet - Vegetation blocking. Pipe - Cannot measure. 3/4 clogged throughout. Outlet - Sediment build up.
205	East Cemetery Rd	Round- open 18in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Fair	Yes	2	Outlet - Road debris blocking outlet.
206	East Cemetery Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
207	East Cemetery Rd	Round- open 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
208	East Cemetery Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
209	East Cemetery Rd	Round- open 13in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Fair	Yes	2	Outlet - Moderate erosion.
210	East Cemetery Rd	Round- open 24in	Metal	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
211	East Cemetery Rd	NS					None	N/A	Fair	Yes	NS			*	Inlet - Sediment and debris obstructing. Pipe - Cannot see pipe buried. Outlet - Cannot see culvert or outlet buried.	
340	East Cemetery Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
341	East Cemetery Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Minor erosion and scour.
342	East Cemetery Rd	NS					NS							*	Inlet - Looks like there used to be something here.	
326	Forrest Tallman Rd	NS					NS		Poor	Yes	NS			*	Inlet - Completely buried on both sides.	
327	Forrest Tallman Rd	Round- open 18in	Metal	Good	NO	0-2'	Wingwalls Only	Masonry	Good	No	None		Good	No	0	
269	Grimes Hill Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Pipe - Half clogged on outlet side. Outlet - Erosion risk of falling in.
270	Grimes Hill Rd	Round- open 18in	Metal	Good	No	2-5'	Wingwalls Only	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Inlet - fallen in. Pipe - Large road crack. Outlet - Medium erosion.
271	Grimes Hill Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Fair	Yes	Wingwalls Only	Masonry	Poor	Yes	5	Inlet - Erosion backing to the road. Outlet - erosion fallen in.
272	Grimes Hill Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Fair	No	3	Pipe - 3/4 clogged.
273	Grimes Hill Rd	Round- open 18in	Plastic	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
274	Grimes Hill Rd	Round- open 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
275	Grimes Hill Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
276	Grimes Hill Rd	Round- open 18in	Metal	Poor	Yes	0-2'	Wingwalls Only	Masonry	Fair	No	Wingwalls Only	Masonry	Fair	Yes	6	Pipe - Corroded on the bottom. Outlet - scour undermining risk of falling.
278	Grimes Hill Rd	Round- open 15in	Metal	Fair	Yes	0-2'	None	N/A	Good	No	Headwall Only	Masonry	Good	No	2	Pipe - Deformed on inlet and corrosion throughout, half clogged at outlet.
280	Grimes Hill Rd	Round- open 12in	Metal	Fair	Yes	0-2'	None	N/A	Good	No	None		Good	No	2	Pipe - 3/4 clogged.
287	Grimes Hill Rd	Round- open 12in	Plastic	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	2	Pipe - Partially Clogged throughout.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
288	Grimes Hill Rd	Round- open 12in	Metal	Poor	Yes	2-5'	None	N/A	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	5	Pipe - Corroded through bottom. Outlet - Minor erosion.
289	Grimes Hill Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	NS				0	Outlet - Unknown cannot access due to fencing.
263	High Bridge Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	Outlet - Minor erosion from the top.
264	High Bridge Rd	Round- open 15in	Metal	Poor	Yes	0-2'	None	N/A	Good	No	Wingwalls Only	Masonry	Fair	Yes	5	Pipe - Corroded through bottom. Outlet - scour undermining.
300	High Bridge Rd	Round- open 18in	Plastic	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
138	Huckins Hill Rd	Round- open 12in	Metal	Fair	Yes	2-5'	Wingwalls Only	Masonry	Fair	Yes	None		Fair	No	5	Inlet - minor erosion. Pipe - 1/2 clogged throughout. Outlet - Minor erosion.
139	Huckins Hill Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Fair	Yes	6	Inlet - Partially blocked by sediment and debris. Pipe - Partially corroded sediment throughout 1/4 clogged. Outlet - Minor erosion.
311	Huckins Hill Rd	Round- open 15in	Metal	Fair	Yes	0-2'	Wingwalls Only	Masonry	Good	No	None		Fair	Yes	4	Pipe - Corroded bottom. Outlet - Erosion around pipe eating back toward road see picture 2.
51	Indian Pond Rd	Round- open 15in	Metal	Fair	No	0-2'	None	N/A	Fair	Yes	None		Good	No	3	Inlet - Vegetation.
91	Indian Pond Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	Yes	None		Fair	Yes	3	Inlet - Vegetation. Outlet - Significant scour undermining culvert up to 2.5 feet.
92	Indian Pond Rd	Round- open 18in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Fair	Yes	3	Outlet - Scour and undermining and vegetation.
93	Indian Pond Rd	Round- open 15in	Metal	Good	No	0-2'	NS				None		Fair	No	*	Inlet - Not surveyable. Buried and high vegetation.
94	Indian Pond Rd	Round- open 12in	Metal	Good	No	2-5'	Wingwalls Only	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
95	Indian Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall Only	Other	Good	Yes	Headwall w/ Wingwalls	Other	Good	No	1	Inlet - Blocked by sediment nd debris.
96	Indian Pond Rd	Round- open 12in	Metal	Fair	Yes	2-5'	Headwall Only	Other	Good	No	None		Fair	No	3	Pipe - Clogged.
97	Indian Pond Rd	Round- open 16in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	2	Pipe - Rusted.
98	Indian Pond Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	No	Headwall w/ Wingwalls	Other	Good	No	1	
99	Indian Pond Rd	Round- open 9in	Metal	Good	No	0-2'	NS				None		Good	No	*	Inlet - Cannot find inlet buried.
101	Indian Pond Rd	Round- open 16in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	Yes	4	Inlet - Falling in. Outlet - Falling in.
102	Indian Pond Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Other	Poor	Yes	Headwall w/ Wingwalls	Other	Good	No	6	Inlet - Erosion. Pipe - Eroded.
106	Indian Pond Rd	Round- open 18in	Other	Poor	Yes	0-2'	Wingwalls Only	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	3	Pipe - Broken and partially clogged and collapsing.
107	Indian Pond Rd	Round- open 18in	Plastic	Good	No	0-2'	None	N/A	Fair	Yes	Headwall w/ Wingwalls	Other	Good	No	2	Inlet - Half blocked with sediment and debris.
108	Indian Pond Rd	Round- open 12in	Metal	Fair	No	0-2'	Headwall Only	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	No	4	Inlet - Headwall falling in 3/4 blocked with sediment and debris.
109	Indian Pond Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall Only	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	Yes	2	Outlet - Minor erosion.
110	Indian Pond Rd	Round- open 15in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Good	No	4	Inlet - Clear out sediment and debris. Pipe - Partially clogged with leaves and sediment.
111	Indian Pond Rd	Round- open 12in	Metal	Fair	Yes	2-5'	None	N/A	Good	No	None		Fair	Yes	4	Pipe - 3/4 clogged. Outlet - Road washing out.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
112	Indian Pond Rd	Round- open 12in	Metal	Good	No	0-2'	None	N/A	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	Yes	4	Inlet - Vegetation. Outlet - Headwall fell in.
113	Indian Pond Rd	Round- open 15in	Metal	Poor	Yes	2-5'	None	N/A	Fair	Yes	None		Good	No	5	Inlet - Leaves and sediment. Pipe - 3/4 clogged.
114	Indian Pond Rd	Round- open 12in	Metal	Fair	Yes	0-2'	None	N/A	Good	No	None		Fair	Yes	4	Pipe - Half clogged. Outlet - Vegetation.
290	Indian Pond Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall Only	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	3	Pipe - Eroded bottom.
291	Indian Pond Rd	Round- open 15in	Metal	Fair	Yes	0-2'	Headwall Only	N/A	Poor	Yes	None		Fair	Yes	7	Inlet - Blocked by rocks and vegetation. Pipe - 1/4 clogged rusty. Outlet - Vegetation.
158	Lower Stonehouse Mountain Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
159	Lower Stonehouse Mountain Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
160	Lower Stonehouse Mountain Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
161	Lower Stonehouse Mountain Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	None		Good	No	2	Inlet - Sediment build up in ditch.
333	Marsh Rd	NS					NS								*	Inlet - Not surveyable might be one here.
189	Mousley Brook Rd	Elliptical- open 24in x 10in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Poor	Yes	4	Pipe - Downstream scour. Outlet - Scour pipe perched over 2 feet high erosion see photos.
190	Mousley Brook Rd	NS					NS								*	Inlet - Not surveyable vegetation and electric fence.
191	Mousley Brook Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall Only	Other	Good	No	Wingwalls Only	Other	Fair	No	1	Outlet - looks prone to washouts.
192	Mousley Brook Rd	Elliptical- open 12in x 18in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	No	2	
328	Mousley Brook Rd	Round- open 14in	Metal	Poor	Yes	0-2'	None	N/A	Fair	Yes	None		Poor	Yes	8	Inlet - Vegetation maintenance needed. Pipe - Corroded. Outlet - Poor gps; road looks like it will fall in and block outlet.
329	Mousley Brook Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	None		Good	No	2	Inlet - Minor erosion; vegetation.
330	Mousley Brook Rd	Round- open 16in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only		Fair	Yes	2	Outlet - Minor Erosion.
331	Mousley Brook Rd	Elliptical- open 8in x 15in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	No	NS				*	Pipe - Clogged on inlet ; unable to assess outlet due to electric fence.
332	Mousley Brook Rd	Elliptical- open 10in x 17in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Wingwalls Only	Other	Good	No	0	Pipe - 10 inches open on inlet.
126	Mud Turtle Pond Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Risk of falling in partially blocking.
127	Mud Turtle Pond Rd	Elliptical- open 30in x 24in	Metal	Fair	Yes	0-2'	Wingwalls Only	Masonry	Fair	Yes	Wingwalls Only	Masonry	Good	No	4	Inlet - scour undermining. Pipe - Corroded.
128	Mud Turtle Pond Rd	Round- open 15in	Plastic	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Wingwalls Only	Masonry	Good	No	2	Pipe - Half clogged on outlet side.
129	Mud Turtle Pond Rd	Round- open 24in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	3	Pipe - Bottom corroded.
130	Mud Turtle Pond Rd	NS					NS				NS				*	Inlet - Culvert no longer here but owner of adjacent property says there are problems here.
131	Mud Turtle Pond Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
132	Mud Turtle Pond Rd	Round- open 24in	Plastic	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
133	Mud Turtle Pond Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
134	Mud Turtle Pond Rd	Round- open 15in	Metal	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Scour undermining.
135	Mud Turtle Pond Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
136	Mud Turtle Pond Rd	Round- open 12in	Metal	Fair	Yes	0-2'	Wingwalls Only	Masonry	Fair	Yes	None		Good	No	4	Inlet - partially obstructing pipe. Pipe - Partially corroded through.
137	Mud Turtle Pond Rd	Round- open 18in	Metal	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
307	Mud Turtle Pond Rd	Round- open 6in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
308	Mud Turtle Pond Rd	Round- open 8in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
309	Mud Turtle Pond Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	Outlet - Looks new and unfinished if no headwall there is concern for road erosion.
310	Mud Turtle Pond Rd	Round- open 24in	Metal	Poor	Yes	0-2'	Wingwalls Only	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Fair	Yes	7	Inlet - scour undermining. Pipe - Bottom corroded through. Outlet - Scour undermining.
79	Norris Rd	Round- open 18in	Metal	Good	No	2-5'	Catch Basin	Precast Concrete	Good		Wingwalls Only	Other	Good	No	0	Catchbasin - Cannot see well.
80	Norris Rd	NS					NS				NS			*	Catchbasin - Clogged with sand cannot assess.	
82	Norris Rd	Round- open 18in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	Yes	5	Inlet - Minor falling in. Pipe - Starting to erode bottom. Outlet - Falling in.
83	Norris Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	3	Pipe - Bottom eroded.
84	Norris Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	2	Pipe - Partially clogged 1/2.
85	Norris Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Other	Fair	No	Wingwalls Only	Other	Good	No	4	Pipe - Bottom eroded.
86	Norris Rd	Round- open 18in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Other	Fair	No	Headwall w/ Wingwalls	Other	Fair	Yes	6	Inlet - Minor erosion. Pipe - Bottom eroded. Outlet - Fallen stones and partially obstructing.
87	Norris Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
88	Norris Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Other	Fair	No	Headwall w/ Wingwalls	Other	Good	No	4	Pipe - Bottom completely eroded.
293	Norris Rd	NS					Catch Basin	Precast Concrete	Good	No	NS				*	Pipe - Not able to measure pipe. Catchbasin - Water coming in from up Norris unknown.
294	Norris Rd	NS					Catch Basin	Precast Concrete	Good	No	NS				*	Pipe - Unable to assess pipe.
140	Orfordville Rd	NS					NS				NS				*	Inlet - Possible pipe under town road cannot find end.
143	Orfordville Rd	Round- open 15in	Metal	Good	No	2-5'	None	N/A	Good	No	None		Good	No	0	
144	Orfordville Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
145	Orfordville Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
146	Orfordville Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Poor	Yes	3	Pipe - Cannot take photo. Set back on inlet and blocked on outlet. Outlet - Blocking pipe.
148	Orfordville Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
149	Orfordville Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Leaves and acorns.
150	Orfordville Rd	Round- open 9in	Metal	Good	Yes	2-5'	None	N/A	Poor	Yes	None		Good	No	3	Inlet - Buried. Pipe - Inlet buried.
151	Orfordville Rd	Round- open 15in	Metal	Poor	Yes	0-2'	None	N/A	Good	No	None		Fair	Yes	5	Pipe - Clogged on outlet side. Outlet - Sediment build up.
152	Orfordville Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Wingwalls Only	Masonry	Good	No	0	
153	Orfordville Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
155	Orfordville Rd	Round- open 12in	Metal	Fair	No	2-5'	Headwall Only	Masonry	Fair	Yes	None		Poor	Yes	6	Inlet - Half blocked by sediment and gravel. Outlet - Looks like headwall fell.
313	Orfordville Rd	Elliptical- open 34in x 20in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
314	Orfordville Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
315	Orfordville Rd	Round- open 15in	Plastic	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
235	Piermont Heights Rd	Round- open 15in	Concrete	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	None		Good	No	4	Inlet - Minor erosion and falling in. Pipe - 1/2 clogged.
237	Piermont Heights Rd	NS					NS				NS				*	Inlet - Markers here but cannot find pipe may be advisory markers.
240	Piermont Heights Rd	NS	Metal	Poor	Yes	0-2'	None	N/A	Fair	Yes	Headwall Only	Masonry	Fair	Yes	7	Inlet - Sediment and debris blocking. Pipe - 3/4 clogged throughout. Outlet - Sediment build up.
241	Piermont Heights Rd	Round- open 15in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	1	Pipe - Almost corroded through.
242	Piermont Heights Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	2	Pipe - Partially corroded through.
243	Piermont Heights Rd	Round- open 18in	Metal	Fair	No	0-2'	Headwall Only	Masonry	Good	No	Headwall Only	Masonry	Good	No	1	Pipe - Slightly deformed.
244	Piermont Heights Rd	Round- open 15in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	1	Pipe - Starting to corrode through bottom.
245	Piermont Heights Rd	Round- open 18in	Metal	Good	No	0-2'	None	N/A	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
248	Piermont Heights Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
343	Piermont Heights Rd	Round- open 18in	Plastic	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
344	Piermont Heights Rd	Round- open 15in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	1	Pipe - 1/4 clogged with sand.
255	Prettyman Rd	Round- open 18in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
256	Prettyman Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Partially fallen in and sediment build up blocking pipe.
257	Prettyman Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Inlet - A little erosion behind. Pipe - Clogged half at outlet side. Outlet - Sediment and debris build up.
258	Prettyman Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
165	Quinttown Rd	Round- open 12in	Plastic	Fair	Yes	2-5'	Headwall w/ Wingwalls	Other	Poor	Yes	None		Good	No	5	Inlet - Sediment build up headwall fallen in vegetation. Pipe - Deformed inlet side.
167	Quinttown Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall Only	Other	Fair	No	None		Good	No	1	

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
168	Quinttown Rd	Round- open 18in x 13in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Other	Fair	No	Wingwalls Only	Other	Fair	Yes	5	Pipe - Squished quarter clogged inlet. Outlet - Minor Erosion.
169	Quinttown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	No	Headwall Only	Other	Fair	Yes	3	Outlet - Roadway erosion behind headwall see photos.
170	Quinttown Rd	Round- open 15in	Metal	Fair	No	2-5'	None	N/A	Good	No	Headwall Only	Other	Poor	Yes	4	Pipe - Pipe deformed see outlet. Outlet - Headwall at risk of blocking pipe; high erosion undermining.
171	Quinttown Rd	Round- open 18in	Metal	Poor	Yes	0-2'	None	N/A	Good	No	None		Good	No	3	Pipe - Eroded pipe.
172	Quinttown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Fair	No	1	
173	Quinttown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	No	3	Inlet - Erosion at risk of caving in. Outlet - Minor erosion.
174	Quinttown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
175	Quinttown Rd	Round- open 18in	Metal	Good	No	0-2'	Wingwalls Only	Other	Fair	No	Headwall w/ Wingwalls	Other	Good	No	1	Inlet - Minor erosion.
176	Quinttown Rd	Round- open 18in	Metal	Good	No	0-2'	Wingwalls Only	Other	Good	No	Wingwalls Only	Other	Fair	Yes	2	Outlet - Minor Erosion.
177	Quinttown Rd	Round- open 18in	Metal	Fair	Yes	2-5'	None	N/A	Good	No	Headwall w/ Wingwalls	Other	Good	No	2	Pipe - 1/4clogged at outlet. Outlet - Runoff from road causing some erosion nearby.
179	Quinttown Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall Only	Other	Good	No	0	
180	Quinttown Rd	Round- open 16in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	
181	Quinttown Rd	Round- open 22in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Poor	Yes	Headwall Only	Other	Fair	Yes	6	Inlet - Fallen in. Outlet - Vegetation blocking flow.
182	Quinttown Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	No	3	Inlet - Danger of rocks falling in.
183	Quinttown Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall Only	Other	Good	No	Headwall Only	Other	Good	No	0	
184	Quinttown Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall Only	Other	Good	No	Wingwalls Only	Other	Good	No	0	Pipe - Poor gps.
187	Quinttown Rd	Round- open 8in	Metal	Good	No	0-2'	Headwall Only	Other	Good	No	Headwall Only	Other	Good	No	0	
334	Quinttown Rd	Round- open 18in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	1	
335	Quinttown Rd	Round- open 16in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Other	Fair	Yes	Headwall Only	Other	Fair	No	3	Inlet - Minor erosion.
336	Quinttown Rd	Round- open 15in x 10in	Metal	Fair	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	1	Pipe - Outlet side partially clogged.
337	Quinttown Rd	Round- open 18in	Metal	Fair	No	2-5'	Wingwalls Only	Other	Fair	Yes	Headwall w/ Wingwalls	Other	Fair	No	4	Inlet - Minor erosion.
47	River Rd	Round- open 15in	Metal	Poor	Yes	0-2'	None	N/A	Good	No	None		Fair	Yes	5	Pipe - Completely clogged. Outlet - Blocked up.
302	Sawyer Brook Rd	Round- open 24in	Plastic	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Minor erosion running from road.
303	Sawyer Brook Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
304	Sawyer Brook Rd	Round- open 18in	Plastic	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0	
305	Sawyer Brook Rd	Round- open 24in	Plastic	Good	No	2-5'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
306	Sawyer Brook Rd	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Fair	Yes	None		Good	No	2	Inlet - Minor erosion and build up of sediment and debris.
116	Strawberry Hill Rd	Round- open 12in	Metal	Poor	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Poor	Yes	6	Pipe - Pipe deformed and clogged. Outlet - Road falling in and erosion.
117	Strawberry Hill Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
118	Strawberry Hill Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Wingwalls Only	Masonry	Good	No	None		Good	No	2	Pipe - One third clogged.
119	Strawberry Hill Rd	Round- open 15in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	1	
120	Strawberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Mild erosion behind.
121	Strawberry Hill Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Pipe - Corroding. Outlet - Erosion risk of falling.
122	Strawberry Hill Rd	Elliptical- open 30in x 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Partially fallen in.
123	Strawberry Hill Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
124	Strawberry Hill Rd	Round- open 18in	Metal	Fair	Yes	2-5'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	2	Pipe - Partially corroded.
125	Strawberry Hill Rd	Round- open 12in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
311	Strawberry Hill Rd	Round- open 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
20	Tillitson Falls Rd	Round- open 15in	Metal	Fair	No	0-2'	Wingwalls Only	Other	Good	No	Wingwalls Only	Other	Good	No	1	
62	Tillitson Falls Rd	Round- open 15in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Medium erosion.
63	Tillitson Falls Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Wingwalls Only	Masonry	Fair	No	None		Good	No	3	Pipe - About to corrode through.
64	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Partially fallen in.
65	Tillitson Falls Rd	Round- open 18in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	5	Pipe - Corroded through bottom. Outlet - Medium erosion.
66	Tillitson Falls Rd	Round- open 15in	Metal	Fair	Yes	0-2'	Headwall Only	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Fair	Yes	6	Inlet - Sediment and debris blocking and erosion. Pipe - Corroded on outlet side. Outlet - Scour undermining.
68	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Fair	No	None		Good	No	1	
69	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
70	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
72	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Wingwalls Only	Masonry	Good	No	None		Fair	No	1	
73	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
74	Tillitson Falls Rd	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
75	Tillitson Falls Rd	Round- open 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	2	Outlet - Half fallin in.
76	Tillitson Falls Rd	NS		Poor	Yes		Headwall w/ Wingwalls	Masonry	Poor	Yes	Headwall w/ Wingwalls	Masonry	Good	No	6	Inlet - Blocked by debris falling. Pipe - Cannot find pipe buried.

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin					Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments	
77	Tillitson Falls Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
89	Town Road 100	Round- open 24in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Other	Good	No	None		Good	No	0		
249	Town Road 107	Round- open 15in	Metal	Good	No	0-2'	None	N/A	Fair	Yes	Headwall Only	Masonry	Good	No	2	Inlet - Sediment build up.	
251	Town Road 107	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
345	Town Road 107	NS	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Poor	Yes	Wingwalls Only	Masonry	Fair	Yes	7	Inlet - Sediment and debris blocking. Pipe - 1/2 Clogged throughout cannot get size. Outlet - sediment and debris blocking.	
346	Town Road 107	Round- open 12in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	2	Pipe - Partially corroded.	
164	Town Road 79	Round- open 24in	Plastic	Good	No	0-2'	None	N/A	Good	No	None		Good	No	0		
246	Town Road 85	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Fair	Yes	2	Outlet - Debris blocking.	
247	Town Road 85	Round- open 18in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Wingwalls Only	Masonry	Fair	Yes	2	Outlet - erosion from road along pipe.	
212	Town Road 86	Round- open 12in	Metal	Good	No	0-2'	None	N/A	Good	No	Headwall Only	Masonry	Good	No	0		
213	Town Road 86	Round- open 15in	Plastic	Good	No	0-2'	None	N/A	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
214	Town Road 86	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Sediment and debris blocking inlet.	
215	Town Road 86	Round- open 15in	Metal	Good	No	0-2'	Headwall Only	Masonry	Fair	Yes	None		Good	No	2	Inlet - Minor sediment build up blocking inlet.	
45	Townshed Rd	Round- open 12in	Plastic	Good	No	0-2'	None	N/A	Fair	Yes	None		Good	No	2	Inlet - Minor blocking. Pipe - Outlet plastic pipe, inlet deformed.	
46	Townshed Rd	Round- open 18in	Metal	Fair	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	2	Pipe - End of pipe at outlet rusted and deformed.	
299	Townshed Rd	Round- open 15in	Metal	Good	No	0-2'	Wingwalls Only	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - debris and leaves.	
50	Upper Baker Pond Rd	Round- open 24in	Metal	Good	No	0-2'	Catch Basin	Precast Concrete	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
217	Upper Baker Pond Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0		
218	Upper Baker Pond Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	None		Good	No	2	Inlet - Partially blocked with sediment and debris.	
219	Upper Baker Pond Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
220	Upper Baker Pond Rd	Round- open 18in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Scour undermining and erosion of wingwalls.	
221	Upper Baker Pond Rd	Round- open 15in	Plastic	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Fair	Yes	None		Good	No	2	Inlet - Sediment build up partially blocking pipe.	
222	Upper Baker Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Fair	No	Headwall w/ Wingwalls	Masonry	Good	No	1	Inlet - Minor erosion.	
223	Upper Baker Pond Rd	Round- open 24in	Metal	Good	No	0-2'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0		
224	Upper Baker Pond Rd	Round- open 12in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	2	Pipe - Deformed a bit on outlet blocking flow.	
225	Upper Baker Pond Rd	Round- open 15in	Metal	Fair	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	3	Pipe - 1/4 clogged on outlet side. Outlet - Sediment build up partially blocking outlet.	

Town of Orford Culvert Inventory, 2019

Drainage

Drainage Culverts are graded as **Good (0-3)**, **Fair (4-6)**, **Poor (7-9)**, and **Incomplete (*)**. NS indicates data that was Not Surveyable. See supplementary document for further details on the drainage score rating. The data contained in this document is for planning purposes only. This Tabular Report was created in December 2019 by UVLSRPC.



		Pipe					Inlet or Catch Basin				Outlet				Results	
Town ID	Street	Shape	Material	Condition	Needs Maintenance?	Height of Fill	End Treatment	Material	Condition	Needs Maintenance?	End Treatment	Material	Condition	Needs Maintenance?	Score	Comments
226	Upper Baker Pond Rd	Round- open 18in	Metal	Good	No	2-5'	None	N/A	Fair	Yes	None		Good	No	2	Inlet - Minor erosion.
227	Upper Baker Pond Rd	Round- open 18in	Metal	Good	No	2-5'	None	N/A	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	2	Inlet - Minor erosion.
228	Upper Baker Pond Rd	Round- open 15in	Metal	Poor	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	5	Pipe - Hole in ground by marker possibly due to culvert damage. Outlet - Falling in.
229	Upper Baker Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
230	Upper Baker Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
231	Upper Baker Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
232	Upper Baker Pond Rd	Round- open 15in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
233	Upper Baker Pond Rd	Round- open 15in	Concrete	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Fair	Yes	2	Outlet - Sediment build up partially obstructing.
234	Upper Baker Pond Rd	Round- open 15in	Concrete	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	None		Good	No	0	
347	Upper Baker Pond Rd	Round- open 12in	Plastic	Good	No	2-5'	Headwall Only	Masonry	Good	No	Headwall w/ Wingwalls	Other	Good	No	0	Outlet - Wood around structure for driveway.
348	Upper Baker Pond Rd	Round- open 15in	Metal	Fair	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	Good	No	4	Inlet - Half blocked by sediment build up. Pipe - 3/4 clogged throughout.
316	Upper Stonehouse Mountain Rd	Round- open 18in	Metal	Fair	Yes	2-5'	Wingwalls Only	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Fair	Yes	4	Pipe - Partially corroded through. Outlet - Scour undermining.
317	Upper Stonehouse Mountain Rd	NS		Poor	Yes	0-2'	Headwall w/ Wingwalls	Masonry	Poor	Yes	Headwall w/ Wingwalls	Masonry	Fair	Yes	8	Inlet - Blocking pipe. Pipe - Pipe buried and clogged cannot fully assess. Outlet - Minor erosion and blocked with sediment.
318	Upper Stonehouse Mountain Rd	NS	Metal	No Rating	Yes	2-5'	Headwall w/ Wingwalls	Masonry	Fair	Yes	Headwall w/ Wingwalls	Masonry	No Rating	Yes	*	Inlet - Sediment and debris blocking pipe. Pipe - Blocked by sediment on both sides. Outlet - Might be blocking pipe.
319	Upper Stonehouse Mountain Rd	Round- open 18in	Metal	Good	No	2-5'	Headwall w/ Wingwalls	Masonry	Good	No	Headwall w/ Wingwalls	Masonry	Poor	Yes	3	Pipe - Noticed that about 30 ft down the road there is a lot of washout that may indicate culvert problems here. Outlet - Fallen in.
320	Upper Stonehouse Mountain Rd	Round- open 24in	Metal	Good	No	2-5'	None	N/A	Good	No	Headwall w/ Wingwalls	Masonry	Good	No	0	
321	Upper Stonehouse Mountain Rd	NS		Poor	Yes		Headwall Only	Masonry	Poor	Yes	NS		Poor	Yes	9	Inlet - Sediment build up cannot see pipe. Pipe - fully clogged and blocked cannot find outlet. Outlet - Cannot find.